

SERVICE BULLETIN



THE

Indian

MOTORCYCLE COMPANY

Bulletin No. SVB-133**Model** ME**Subject** Swing Arm Bolt**Date** 2/15/73

ME-76 SWING ARM BOLT

On some ME-76 swing arm bolts the nut will bottom out before the bolt is tight against the frame. This can be detected by excessive play in the rear swing arm where it attaches to the frame. If this problem exists, simply add more flat washers as necessary behind the swing arm nut. This will prevent the nut from bottoming out against the threads.

