

SERVICE BULLETIN



THE
Indian
MOTORCYCLE COMPANY

Bulletin No.	SVB-114/1
Model	MM-5A and JC-5A
Subject	Modifications
Date	11-20-72

Cut the head pipe (M24-21) off approximately 1-1/2 inches from the flange. Cut the original muffler head pipe off to match the new exhaust head pipe, and weld together.

PARTS LIST

<u>Quantity</u>	<u>Part Number</u>	<u>Description</u>
1	SHA-14.14	Carburetor
2	C-1486	Main Jet
1	RI-101	Air Cleaner
1	M24-13	Cylinder
1	M24-12	Head
10	25-4001	Washers
1	M2-10	Base Gasket
1	M2-11	Head Gasket
1	M38-39	Intake Gasket
1	A24-31	Piston Kit 38.8
1	M24-161-14.14	Intake Manifold
2	M1-33	Intake Washer
2	M3-17	Intake Bolt
1	M24-21	Head Pipe
1	M6-10	Head Pipe Nut
1	M6-11	Head Pipe Gasket

