



# FACTORY SERVICE BULLETIN

<b>Number</b>	SVB-173
<b>Model</b>	MM-5A JC-5A
<b>Subject</b>	KICK START SHAFT

## KICK START SHAFT – S5K2 ENGINE

The kick start shaft has been changed to engage the ratchet mechanism more positively. The new shaft (#58-10-1052/1) and the old shaft (#58-10-1052) are interchangeable. The only difference is the location of the snap ring groove.

The shaft should be "shimmed" so that there is only .002 to .004 end play. (Refer to SVB-147)



